



Release the Lock/Hold Lever before weighing or turning the Zero Adjust Knob.
Lock the Lock/Hold Lever when transporting scale.

To weigh oversize items:

- Place item on scale and allow to stabilize
- Press Lock/Hold Lever down
- Remove item from scale
- Read weight
- Release Lock/Hold Lever

3 Year Limited Warranty - Not Legal For Trade